UNITED STATES CONSUMER PRODUCT SAFETY IMPROVEMENT ACT (CPSIA) SECTION 102

CERTIFICATE OF CONFORMITY

UNIQUE IDENTIFIER:	VIRCO C0C065

PRODUCT/SERIES DESCRIPTION Virco 723 Series

ITEM /SERIES:

All 723 Series units inclusive of models 723, 723M, 723CHRM, and 723W, including the various configurations, options and finishes.

CERTIFICATION: BASED ON A REASONABLE TEST PROGRAM, THIS PRODUCT COMPLIES WITH ALL RULES, BANS, STANDARDS, OR REGULATIONS APPLICABLE TO THE PRODUCT UNDER THE CPSIA OR ANY OTHER ACT ENFORCEABLE BY THE CPSC INCLUDING (List all rules, bans, standards and applicable to the product):

- 21 C.F.R. Part 1303 (Ban of Lead-Containing Paint and Certain Consumer Products Bearing Lead-Containing Paint).
- Consumer Product Safety Improvements Act (CPSIA) Section 101 (a)(2)(B).

CERTIFICATION DATE:

January 17, 2024

CERTIFIED BY:

MANUFACTURER NAME: ADDRESS: CITY STATE/PROVINCE: ZIP/POSTAL CODE: COUNTRY: Virco Mfg. Corporation 2027 Harpers Way Torrance, California 90501 USA

DATE AND PLACE OF MANUFACTURE:

NOTICE	The next two digits, which are always in the range of 01 to 99, indicate the assembly line on which the labeled product was manufactured; 01= assembly line 1, and so on
D PREVENT STRUCTURAL FAILURES AND POSSIBLE INJURY, FURNITURE HOULD NOT BE USED OTHER THAN FOR ITS INTENDED PURPOSE AND HOULD BE INSPECTED REGULARLY FOR LOOSE OR MISSING BERENS IR RIVETS, METAL FATIQUE, CRACKS, BROKEN WELDS, MISSING ATTACHMENTS, LOOSE STAPLES, AND GENERAL INSTABLITY.	The next digit, which is always in the range of 1 to 3, indicates the shift during which the labeled product was manufactured: 1= first shift, and so on.
URNITURE THAT IS DAMAGED OR APPEARS TO BE UNSTABLE SHOULD MULEDIATELY BE REMOVED FROM SERVICE, REPORTED TO THE FACILITY ANAGER, AND REPLACED OR REPAIRED. OR INFORMATION ON FURNITURE MAINTENANCE, OR TO REPORT	The next two digits, which are always in the range of 01 to 31, indicate the specific day of the production month; 01= the first of the month, and so on.
URNITURE WHICH REQUIRES SERVICE, CALL VIRCO TOLL FREE AT -BOO 44VIRCO. REPAIRS SHOULD GNLY BE MADE USING FACTORY UTHORIZED PARTS AND METHODS.	The next digit, which is always a letter in the range of A to L, indicates the production month; A=January, B=February, and so on.
M-2945 BLK01-CHRM 29459C59	The next two digits indicate the production year; 00- the year 2000, 01-2001, and so on.
0 ¹¹¹ 46231*72318 ¹¹ 9	The first digit, which is always either 1 or 2, indicates the manufacturing site of the labeled product; 1–Virco Torrance, CA and 2–Virco Torrawy, AR,

TEST DATE:

January 17, 2024

THIRD PARTY TEST LABORATORY:

ADDRESS: CITY STATE/PROVINCE: ZIP/POSTAL CODE: COUNTRY: Applied Technical Services, Incorporated 1049 Triad Court Marietta, Georgia 30062 U.S.A.

RECORDS CONTACT:

NAME: COMPANY: ADDRESS: CITY, STATE ZIP CODE: PHONE NUMBER: E-MAIL ADDRESS: Scott L. Fletcher, V.P. Engineering Virco Mfg. Corporation 2027 Harpers Way Torrance, California 90501 (310) 533-0474 ScottFletcher@virco.com